



Nebraska Handyman
 1500 Adams Street
 Blair NE 68008
 (402) 699-3022
 WWW.NEBRASKAHANDYMAN.COM

Roofing Inspection Checklist

Water Leaks	List All Water Leaks No Water Leaks
Shingles	List All Damaged or Missing Shingles No Damaged or Missing Shingles
Flashing	Check All Roof Flashing No Damaged Flashing – All Flashing is Installed Correctly
Roof Attachments	Check All Roof Attachments No Damages or Incorrectly Installed Attachments – 2 Vents, 1 Brick Chimney
Gutters	Check All Gutters No Damaged or Leaking Gutters
Ventilation	Check Roof/Attic Ventilation Roof Properly Ventilated
Wear/Aging	List All Roof Wear/Aging Roof is in good condition, roof installed on 2/12/2016

Address of Inspected Roof: 123 Nebraska Street
Roofing NE 12345

Signature of Inspector: Jason Crawford Date of Inspection: 9/26/2018